



Aperio GT 450 1.1.3 Patch Notice

Leica Biosystems is always looking for ways to further improve our customers' experience using our products. Our software patches often include new features, but also include improvements based on customer input and our own internal testing. Please make sure to read below for the details of this patch so you can get the best out of your product. Thank you for being a customer of Leica Biosystems.

Aperio GT 450 1.1.3 Patch Update

Affected component: Controller

This patch release updates the homing process in the scanner.

Aperio GT 450 1.1.3 Patch Notice
Part Number/Revision: PN-0037, Revision A
Date: February 2023

This document applies to Aperio GT 450 Controller, Aperio GT 450 Console, and Aperio GT 450 SAM version 1.1.3.

Copyright Notice

- ▶ Copyright © 2023 Leica Biosystems Imaging, Inc. All Rights Reserved. LEICA and the Leica logo are registered trademarks of Leica Microsystems IR GmbH. Aperio, GT, and GT 450 are trademarks of Leica Biosystems Imaging in the USA and optionally in other countries. Other logos, product and/or company names might be trademarks of their respective owners.
- ▶ This product is protected by registered patents. For a list of patents, contact Leica Biosystems.

User Resources

- ▶ For the latest information on Leica Biosystems Aperio products and services, please visit www.LeicaBiosystems.com/Aperio.

Contact Information – Leica Biosystems Imaging, Inc.

Headquarters	Customer Support
 Leica Biosystems Imaging, Inc. 1360 Park Center Drive Vista, CA 92081 USA Tel: +1 (866)-478-4111 (toll free) Direct International Tel: +1 (760) 539-1100	Contact your local support representative with any query and service request. www.leicabiosystems.com/contact-us/

Revision Record

Rev	Issued	Sections Affected	Detail
A	February 2023	All	New document.



23GT450, 23GT450SAM